



STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

1315 W. 4th Avenue • Kennewick, Washington 99336-6018 • (509) 735-7581

April 23, 2003

Mr. Keith Klein
United States Department of Energy
P. O. Box 550, MSIN: A7-50
Richland, Washington 99352

Mr. Keith Thomson
Fluor Hanford Incorporated
P.O. Box 1000, MSIN: H5-20
Richland, Washington 99352

Mr. Michael Hughes
Bechtel Hanford Incorporated
3350 George Washington Way, MSIN: H0-04
Richland, Washington 99352

RECEIVED
MAY 07 2003

EDMC

Dear Messrs. Klein, Thomson and Hughes:

Re: Completion of inspection of hazardous waste accumulation areas

On April 8, 2003, the Washington State Department of Ecology conducted an inspection of hazardous waste accumulation areas at selected facilities throughout the Hanford Site. Facilities inspected included the following:

- 2025E waste accumulation areas operated by Fluor Hanford Incorporated (FH).
- 331 Building and 3720 Building Laboratories operated by Pacific Northwest National Laboratories (PNNL).
- 100N waste accumulation areas operated by Bechtel Hanford Incorporated (BHI).
- 209E waste accumulation area operated by CH2M Hill Hanford Group (CHG).
- Waste Treatment Plant waste accumulation areas operated by Bechtel National Incorporated (BNI).

Messrs. Klein, Thomson and Hughes
April 23, 2003
Page 2

No violations were revealed at the FH or BHI facilities inspected.

If you have any questions regarding this letter, please contact me at (509) 736-3031.

Sincerely,



Bob Wilson
Compliance Specialist
Nuclear Waste Program

BW:nc

cc: Ray Collins, BHI
Paul Martin, FH
Todd Martin, HAB
Rick Gay, CTUIR
Pat Sobotta, NPT
Russell Jim, YN
Ken Niles, OOE
Administrative Record